

State of New Jerzey

DEPARTMENT OF ENVIRONMENTAL PROTECTION

CHRIS CHRISTIE
Governor

KIM GUADAGNO

Li. Governor

Office of Quality Assurance
401 East State Street
P.O. Box 420, Mail Code 401-02D
Trenton, New Jersey 08625
Telephone: (609)-292-3950
Facsimile: (609)-777-1774

October 31, 2014

BOB MARTIN

Commissioner

CERTIFIED MAIL
RETURN RECEIPT REQUESTED

Attention Laboratory Manager:

RE: January Water Supply PT Study

As a participant in the National Environmental Laboratory Accreditation Program (NELAP) your business is required to acceptably analyze two out of three Proficiency Testing (PT) Samples for each field of proficiency testing within an 18-month period; and must participate in PT Studies approximately every six months.

Businesses are required to purchase PT Samples from a PT Provider accredited by a TNI approved Proficiency Testing Provider Accreditor (PTPA). A list of accredited PT Providers can be found in Attachment A of this letter. It can also be found at http://www.nelac-institute.org/ptproviders.php.

For the January Water Supply Study businesses are required to purchase and analyze PT Samples for the parameters given on the attached "SDW Parameter Table" (Attachment B) in which they hold New Jersey Certification.

Please also note the following:

- Businesses must assure that for the January Water Supply Study the PT sample(s) are not analyzed less than 5 months, or more than 7 months from the prior sample.
- Businesses must report the PT Sample result with the method in which it holds certification. If a business reports a PT Sample result with a method other than that

in which it holds certification it will be evaluated as failed to submit results and therefore "Unacceptable" and will require the analysis of a make-up study.

- Bold parameters on the table are parameters that are required above and beyond the Field
 of Proficiency Testing (FoPT). Businesses must successfully analyze one PT sample a
 year in order to maintain eligibility to report data to the State of New Jersey for these
 parameters.
- An amended report from the PT Sample Provider will not be accepted by the OQA.
- Raw data records will not be accepted or reviewed to use as justification for data reporting errors.
- For PT Sample results that are found "Unacceptable", other enforcement actions may be taken by the NJDEP in addition to the requirement for analyzing samples in a make-up study.
- For any parameters not detected in the PT Sample the laboratory must report a result of less than the laboratory's Reporting Limit (< RL) to get credit for the analysis of the parameter. If a non-detect is not reported as a less than value no credit will be received for the parameter.

For the January Water Supply Study businesses are required to analyze Pt Samples for each analyte by each method in which they hold New Jersey certification. For example, if a laboratory is certified for Aluminum by USEPA 200.7 and Standard Methods (SM) 3120 the laboratory must analyze and pass a PT sample for both USEPA 200.7 and SM 3120 to retain certification for both methods.

Additionally, PT Samples are to be entered into the sample receipt log as samples and tracked through the analytical process as routine environmental samples. PT Samples received as ampules are to be diluted according to the PT Provider's instructions. The diluted ampule becomes the routine environmental sample, which is then added to a routine sample batch. PT Samples shall not be analyzed multiple times unless routine environmental samples are analyzed multiple times. Results from multiple analyses must be calculated in the same manner as routine environmental samples. The type, composition, concentration and frequency of quality control samples analyzed with the PT Samples shall be the same as with that used for environmental samples. Also, initial and continuing calibrations shall be the same frequency as that used with routine environmental samples.

If you have any questions please contract Rachel Ellis at 609-292-3950.

Sincerely,

Joseph F. Aiello, Manager

Enclosure(s): Attachments A & B